



CofC

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

U.S. Patent No.: 6,869,001 B2

Serial No. : 10/686,665

Filed : October 17, 2003

Issued : March 22, 2005

For : DEVICE FOR THE MAINTENANCE OF SEMI-AUTogenous GRINDING  
MILLS USED IN LARGE-SCALE MINING

**PETITION FOR CERTIFICATE OF CORRECTION  
PURSUANT TO 37 C.F.R. § 1.322 OR § 1.323**

Assistant Commissioner for Patents  
Washington, D. C. 20231

Sir:

Applicants hereby request that the above-identified U.S. patent be corrected in accordance with the attached Certificate of Correction.

I. C.F.R. § 1.322

- The mistake(s) was/were incurred through the fault of the Patent and Trademark Office and is/are clearly disclosed in the records of the Office. Therefore, no fee is due.

II. C.F.R. § 1.323

- At least some of the mistakes were made by the applicant. Therefore, a check in the amount of \$100.00 in payment of the fee set forth in 37 C.F.R. § 1.20(a) is enclosed herewith.

Enclosed herewith is a Form PTO-1050 (in duplicate) listing errors that have been found in the above-identified patent. The error(s) are of a clerical or typographical nature or of minor character and were made in good faith. The requested correction(s) do not constitute new matter or require reexamination.

06/09/2006 SZEWDIE1 00000147 6869001  
01 FC:1811 100.00 OP

06/09/2006 SZEWDIE1 00000084 10606665  
01 FC:1811 -100.00 OP

Void date: 06/09/2006 SZEWDIE1  
06/09/2006 SZEWDIE1 00000084 +10606665  
01 FC:1811 -100.00 OP

JUN 13 2006

III. Accordingly, patentees and their assignee respectfully request that the Patent and Trademark Office issue a Certificate of Correction pursuant to 37 C.F.R. § 1.322 or § 1.323, respectively.



Respectfully submitted,

  
\_\_\_\_\_  
Harry B. Shubin, Reg. No. 32,004  
Attorney for Applicants

MILLEN, WHITE, ZELANO  
& BRANIGAN, P.C.  
Arlington Courthouse Plaza 1  
2200 Clarendon Blvd. Suite 1400  
Arlington, Virginia 22201  
Telephone: (703) 243-6333  
Facsimile: (703) 243-6410

Attorney Docket No.: LOPEZ-0002-C01

Date: June 8, 2006

JUN 13 2006

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.  
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

PATENT NO : 6,869,001 B2

DATED : March 22, 2005

INVENTOR(S) : Luis Ortiz CERDA et al.

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 4, line 30, reads "nut to-be-cut" should read -- nut-to-be-cut --  
Column 4, line 32, reads "nut-e-surfaces," should read -- nut-engaging surfaces --  
Column 5, line 13, reads "a single forged bodies" should read -- a single forged body --  
Column 6, line 3, reads "a main allov" should read -- main alloy --

MAILING ADDRESS OF SENDER: Millen, White, Zelano & Branigan  
2200 Clarendon Blvd Suite 1400  
Arlington, VA 22201

PATENT NO. 6,869,001

No. of additional copies



Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, Washington, DC 20231.

JUN 12 2006